

An Employee Owned Company

Office Locations: Denver (HQ), Parker, Colorado Springs, Fort Collins, Glenwood Springs, and Summit County, Colorado

October 2, 2026

Colorado Aggregate Recycling
Attn: Matt Bustamante
8900 Highway 93, Unit A
Golden, Colorado 80403

Subject: Laboratory Test Results, Class 6 Aggregate Base Course/Recycled Concrete,
2026 Colorado Aggregate Recycling, South Yard, Colorado Springs, Colorado

Project No. 26-1-168

Dear Mr. Bustamante:

Attached are the results of laboratory testing performed on a bulk sample of recycled concrete material submitted to our Denver laboratory by a representative of Colorado Aggregate Recycling. The sample was assigned Kumar & Associates, Inc. (K+A) laboratory sample number 101924. We understand the sample was requested to be tested to evaluate the material's suitability to be classified as the Colorado Department of Transportation (CDOT) Class 6 aggregate base course (ABC). The sample originated from Colorado Aggregate Recycling's South Yard located in Colorado Springs, Colorado. Laboratory testing was performed to determine the material classification parameters, including Atterberg Limits, gradation, and moisture-density relationships (modified Proctor). R-Value (hveem-stabilometer) and Los Angeles abrasion testing were also performed. The results of the testing are summarized in the attached Table 1 and figures.

Based on the testing results, the submitted sample meets the gradation and Atterberg limit specifications for Class 6 ABC presented on Table 703-2 in the CDOT's 2025 *Standard Specifications for Road and Bridge Construction*. The testing indicated the material had an R-value of 79 at an exudation pressure of 300 psi and a 37% loss as evaluated by the Los Angeles abrasion test.

If you have questions or need further information, please call.

Sincerely,
KUMAR & ASSOCIATES, INC.

Justin Cupich, P.E.



JDC/as
Attachments
cc: file



TABLE 1
SUMMARY OF LABORATORY TEST RESULTS
SOUTH YARD (COLORADO SPRINGS)

PROJECT NO.: 26-1-168

PROJECT NAME: 2026 COLORADO AGGREGATE RECYCLING LABORATORY TESTING


DATE RECEIVED: 8/27/2026

SAMPLE NO.	DATE TESTED	MAXIMUM DRY DENSITY (pcf)	OPTIMUM MOISTURE CONTENT (%)	GRADATION		PERCENT PASSING No. 200 SIEVE	ATTERBERG LIMITS		R-VALUE ● 300 PSI	LOS ANGELES ABRASION (ASTM C-131)		SOIL OR BEDROCK TYPE
				GRAVEL (%)	SAND (%)		LIQUID LIMIT (%)	PLASTICITY INDEX (%)		GRADING	PERCENT LOSS (%)	
101924	9/2/26	118.5	10.7	63	32	5.2	29	2	79	B	37	POORLY GRADED GRAVEL WITH SILT AND SAND ABC CLASS 6 (RECYCLED CONCRETE)

These test results apply only to the samples which were tested. the testing report shall not be reproduced, except in full, without the written approval of K & A, Inc

COMPACTION TEST REPORT

Curve No. 101924



Preparation Method _____	
Rammer: Wt. <u>10 lb.</u>	Drop <u>18 in.</u>
Type <u>Manual</u>	
Layers: No. <u>five</u>	Blows per <u>56</u>
Mold Size <u>0.075 cu. ft.</u>	
Test Performed on Material	
Passing <u>3/4 in.</u> Sieve	
%>3/4 in. <u>0</u>	%<No.200 <u>5.2</u>
Atterberg (D 4318): LL <u>29</u>	PI <u>2</u>
NM (D 2216) _____	Sp.G. (D 854) <u>2.6</u>
USCS (D 2487) <u>GP-GM</u>	
AASHTO (M 145) <u>A-1-a</u>	
Date: Sampled <u>8/27/26</u>	
Received <u>8/27/26</u>	
Tested <u>9/2/26</u>	
Tested By <u>AS</u>	

COMPACTION TESTING DATA
ASTM D 1557-12 Method C Modified

	1	2	3	4	5	6
WM + WS	10586.0	10860.0	10951.0	10875.0		
WM	6459.0	6459.0	6459.0	6459.0		
WW + T #1	946.5	676.6	718.5	653.6		
WD + T #1	915.7	637.5	676.2	596.1		
TARE #1	496.2	227.6	310.4	154.4		
WW + T #2						
WD + T #2						
TARE #2						
MOIST.	7.3	9.5	11.6	13.0		
DRY DENS.	112.6	117.6	117.9	114.4		

SIEVE TEST RESULTS

Opening Size	% Passing	Specs.
1"	100	100
3/4"	100	95-100
1/2"	75	
3/8"	60	
#4	37	30-65
#8	28	25-55
#16	21	
#30	16	
#50	11	
#100	7	
#200	5.2	3-12

TEST RESULTS

Maximum dry density = 118.5 pcf

Optimum moisture = 10.7 %

Project No. 26-1-168 Client: Colorado Aggregate Recycling
Project: Colorado Aggregate Recycling - 2026 Various Laboratory Projects

Location: South Yard (Colorado Springs) Sample Number: 101924

Kumar & Associates, Inc.

Denver, Colorado

Material Description

poorly graded gravel with silt and sand
ABC Class 6 (Recycled Concrete)

Remarks:

Checked by: JJM


Title: Lab Manager

Figure

These test results apply only to the samples which were tested. the testing report shall not be reproduced, except in full, without the written approval of K & A, Inc.

Particle Size Distribution Report

ASTM C136



% +3"	% Gravel		% Sand			% Fines	
	Coarse	Fine	Coarse	Medium	Fine	Silt	Clay
0	0	63	11	13	8	5	

Test Results (ASTM C136)				
Sieve Size or Diam. (mm.)	Finer (%)	Spec.* (%)	Out of Spec. (%)	Pct. of Fines
1"	100	100		
3/4"	100	95-100		
1/2"	75			
3/8"	60			
#4	37	30-65		
#8	28	25-55		75
#16	21			57
#30	16			42
#50	11			30
#100	7			20
#200	5.2	3-12		14

* CDOT - ABC Class 6

Material Description
poorly graded gravel with silt and sand
ABC Class 6 (Recycled Concrete)

Atterberg Limits
PL= 27 LL= 29 PI= 2

Classification
USCS= GP-GM AASHTO= A-1-a

Test Remarks

Location: South Yard (Colorado Springs)
Sample Number: 101924

Sample Date: 8/27/26

Kumar & Associates, Inc.

Denver, Colorado

Client: Colorado Aggregate Recycling


Project: Colorado Aggregate Recycling - 2026 Various Laboratory Projects

Project No: 26-1-168

Figure

Tested By: JF Checked By: JJM

R-VALUE					
TEST SPECIMEN	1	2	3	4	R-VALUE (300 psi)
MOISTURE CONTENT (%)	18.6	16.9	14.2		79
DENSITY (pcf)	101.7	105.5	108.8		
EXPANSION PRESSURE (psi)	0.000	0.000	0.000		
EXUDATION PRESSURE (psi)	158	326	722		
R-VALUE	78	80	84		



SOIL TYPE: Poorly Graded Gravel with Silt and Sand - ABC Class 6 (Recycled)

LOCATION: South Yard (Colorado Springs)

DATE SAMPLED: 8/27/26

DATE RECEIVED: 8/27/26

DATE TESTED: 9/11/26

GRAVEL: 63

SAND: 32

SILT AND CLAY: 5

LIQUID LIMIT: 29

PLASTICITY INDEX: 2

These test results apply to the samples which were tested. The testing report shall not be reproduced, except in full, without the written approval of Kumar & Associates, Inc. R-value performed in accordance with ASTM D2844. Atterberg limits performed in accordance with ASTM D4318. Sieve analyses performed in accordance with ASTM D422, D1140

26-1-168	KUMAR & ASSOCIATES	HVEEM STABILOMETER TEST RESULTS	101924
----------	--------------------	---------------------------------	--------

Denver (HQ)
2390 South Lipan Street
Denver, CO 80223
Phone: 3037429700

LA Abrasion - Small-Size Coarse Agg

ASTM C131

Client:

Colorado Aggregate Recycling
8900 Highway 93, Unit A
Golden, CO 80403

Project:

26-1-168
Colorado Aggregate Recycling - 2026 Various
Laboratory Projects
8900 Highway 93, Unit A
Golden, CO 80403

Sample Information

Sample Number:	101924	Sample Date:	08/27/2026
Sample From:	Stockpile	Sampling Method:	Not Provided
Location Details:	ABC Class 6 (Recycled Concrete)		
Material Description:	Recycled Base Aggregate	Technician:	Client
Supplier:	Colorado Aggregate Recycling	Plant or Source:	South Yard (Colorado Springs Pit)

Laboratory Test Results

Grading Designation	Nominal Maximum Aggregate Size	Percent Loss (%)
B	19 mm (3/4 inch)	37

Test Completed Date: 08/31/2026

Test Completed By: Kyle Wikowsky